ECS Configuration Change Request					Page 1 of	Pa	age(s)	
1. Originator	2. Log Date:	3. CCR #:	4	4. Rev:	5. Tel:	6. Rm #:	7. Dept.	
Robert Cole	7/24/02	02-0618	-	_	301-925-0799	2110C	SE/HW	
8. CCR Title: Install 2x336 MHz CPUs in p2dis02								
9. Originator Signature/Date			10. Class		11. Type: 12. Need Date: 7/25/02		e: 7/25/02	
Robert Cole /s/ 7/24/02			IN		CCR			
13. Office Manager Signature/Date			14. Category o		fill in Dinak 07)			
James R. Mather /s/ 7/24/02				ECS Ba	aseline Doc. fill in Block 27). Emergency			
5 .			17. Schedule 18. Compact:		18. CI(s) At) Affected:DIPHW		
19. Release Affected by this Change: 20. Date due				to Customer: 21. Estimated Cost:				
N/A				None - Under 100K				
22. Source Reference: ☐NCR (attach) ☐Action Item ☐Tech Ref. ☐GSFC ☐Other:								
23. Problem: (use additional Sheets if necessary) During testing on 7/23/02, p2dis02 ran very low in CPU resources (sar reported an average idle level of zero for fice consecutive 5-minute samples) immediately prior to a system crash.								
24. Proposed Solution: (use additional sheets if necessary) Add a 2x336 MHz CPU board to p2dis02 from p2sps06								
25. Alternate Solution: (use additional sheets if necessary)								
26. Consequences if Change(s) are not approved: (use additional sheets if necessary) A risk of similar crashes and/or poor performance exists								
27. Justification for Emergency (If Block 15 is "Emergency"): This upgrade is desired in time for testing on 7/25/02.								
28. Site(s) Affected: DEDF DEDC DEDC DEDC DEDC DEDC DEDC DEDC								
29. Board Comments:				30. V	Vork Assigned T	o: 31. CCR	Closed Date:	
32. EDF/SCDV CCB Chair (Randall J. Miller /s/	Sign/Date): D 7/24/02 ER	i sposition: A	oproved	App/Co	om. Disapproved	d Withdraw F	wd/ESDIS	
33. M&O CCB Chair (Sign/	Date): D		Approved App/Com. Disapproved Withdraw Fwd/ESDIS ERB Fwd/ECS					
34. ECS CCB Chair (Sign/D	Date): Dis	sposition: Ap	proved A	App/Con	n. Disapproved	l Withdraw F	wd/ESDIS ERB	
		Fwd/ESDIS						